

Miller Drilling Co.

Contractors License No. 324634

Miller Drilling Co.
 329 N. Main St.
 Templeton, CA 93465
 (805) 434-1888

PUMP TEST REPORT

<u>WELL OWNER:</u> Barbara Schriver Dorsett	<u>Pump Set:</u> 210	<u>Job#</u> 18896	<u>Well #:</u> 5"
<u>BILLING ADDRESS:</u> 2372 Our Hill Ln.	<u>Pump Size:</u> 2HP	<u>Well Depth:</u> 220	
Paso Robles, CA	<u>Testing Method:</u> Existing Pump		
93446	<u>Perf Rec:</u> 150-220	<u>APN:</u>	
<u>Standing Level Before Test:</u> 148.32	<u>LOCATION:</u> 2372 Our Hill Place		

TESTING

TIME	PUMPING LEVEL	WATER CONDITION	WATER/BOWLS	GPM
9:00	START			15
9:20	148.42			15
12:00	148.42			15
1:00	148.42			15

Notes: Y: 10.6 B: 10.1 R: 2.5

STANDING LEVEL AFTER TEST: 148.32 after 3 mins
 FINAL TEST RESULTS: Produced: 15 GPM for 4 hours on 9/11/2013
 Test Run By: CHRIS

Abalone Coast Analytical, Inc.

141 Suburban Rd, Ste C-1 San Luis Obispo CA, 93401

Phone: 595-1080 Fax: 595-1080

ELAP #2661

Order #: 13-5409-2

Date/Time Rec'd: 9/11/13 1550

Miller Drilling Company
301 North Main Street
Templeton, CA 93465

Contact: Kurt Bollinger
Phone: 434-1888

Sample #	Sample Description	Date / Time	Analysis	Method	Result	Units	RL	Completed
-2	#18896	9/11/13	Total Coliform	SM 9223 B.	Absent	/100ml	1	09/12/13
	2372 Our Hill Pl.		<i>E-coli</i>	IDEXX	Absent	/100ml	1	09/12/13

Report Completion date:

9/12/13

Reviewed:



Amanda Smith, Lab Director

Definitions

Absent: **Less than 1 CFU/100mLs**

Present: **1 or more CFU/100mLs**

CFU: **Colony Forming Unit**

STATE OF CALIFORNIA
THE RESOURCES AGENCY
DEPARTMENT OF WATER RESOURCES
WATER WELL DRILLERS REPORT

No. 223481

Notice of Intent No. _____
Local Permit No. or Date _____

State Well No. _____
Other Well No. _____

(1) OWNER: Name Richard Sudden
Address * Country Real Estate
City 840 11th St. Paso Robles, CA Zip 93446

(12) WELL LOG: Total depth 240 ft. Depth of completed well 220 ft.
from ft. to ft. Formation (Describe by color, character, size or material)
0 - 2 Top Soil
2 - 25 Yellow Shale
25 - 240 Brown Shale

(2) LOCATION OF WELL (See instructions):
County SIO Owner's Well Number _____
Well address if different from above _____
Township 26S Range 11E Section 25
Distance from cities, roads, railroads, fences, etc. _____
Mtn. Springs Road

APN# 26-291-40

WELL LOCATION SKETCH

(3) TYPE OF WORK:
New Well Deepening
Reconstruction
Reconditioning
Horizontal Well
Destruction (Describe destruction materials and procedures in Item 12)
(4) PROPOSED USE:
Domestic
Irrigation
Industrial
Test Well
Stock
Municipal
Other

NOTE: Any person removing the cap from this well other than Miller Drilling Co. or authorized contractor approved by us will void all structural warranties

(5) EQUIPMENT:
Rotary Reverse
Cable Air
Other Bucket
(6) GRAVEL PACK:
Yes No Size 1/2"
Diameter of bore 9 7/8"
Packed from 50' to 220'

(7) CASING INSTALLED:
Steel Plastic Concrete
(8) PERFORATIONS:
Type of perforation or size of screen

From ft.	To ft.	Dia. in.	Gage or Wall	From ft.	To ft.	Slot size
0	220	5	.214	0	150	Blank
				150	220	Perf.

(9) WELL SEAL:
Was surface sanitary seal provided? Yes No If yes, to depth 50 ft.
Were strata sealed against pollution? Yes No Interval _____ ft.
Method of sealing Cement

Work started 10/26/83 Completed 10/28/83

(10) WATER LEVELS:
Depth of first water, if known 150 ft.
Standing level after well completion 125 ft.

WELL DRILLER'S STATEMENT:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.
SIGNED [Signature] (Well Driller)
NAME Miller Drilling Co. (Person, firm, or corporation) (Typed or printed)
Address 501 No. Main St.
City Templeton, CA 93465 Zip _____
License No. 324634 Date of this report 11/21/83

(11) WELL TESTS: Bail Test: 20 gpm at 140'
Was well test made? Yes No If yes, by whom? _____
Type of test Pump Bailer Air lift
Depth to water at start of test _____ ft. At end of test _____ ft.
Discharge _____ gal/min after _____ hours Water temperature _____
Chemical analysis made? Yes No If yes, by whom? _____
Was electric log made? Yes No If yes, attach copy to this report